

30 GeV synchrotron (MR)

3 GeV synchrotron(RCS)

400 GeV Linac (25Hz)

Hadron

MLF
Materials and Life Science
Experimental Facility

Neutrino

Experiences of remote maintenance for the mercury target system for the pulsed neutron source

Takashi Naoe, Hiroyuki Kogawa, Akiyoshi Futakawa, Hidetaka Kinoshita,
Takashi Wakui, Shuna Fujita, Yoshinori Kikuchi, Taichi Endo, Tetsuya Kai,
Shiho Masuda, Yoshihiko Kawakami, Masahide Harada

Neutron Source Section, MLF Division

J-PARC / JAEA





Outline


- Mercury target system in MLF/J-PARC
- Mercury pump replacement
- Leak from mercury flange
- Mockup experiment for metal seal replacement
- Metal seal replacement
- Power cables replacement
- Summary

Pulsed neutron source in MLF/J-PARC


Materials and Life Science Experimental Facility (MLF)





Proton beam window
Aluminum (A5083)





Neutron target
Liquid mercury with 316SS vessel



Muon target@MLF
Rotating graphite




Power upgrade histories of muon and neutron target



Damage mitigation techniques



- Successfully achieved stable 1 MW operation (MLF goal) for two months in April 2024 using Target #15
- Experienced issues: reduction of insulation resistance pump & cables, flange leak etc....

Mercury target system



- Permanent magnet rotating mercury pump, drives mercury by Lorentz force and completely enclosed structure, was adopted to eliminate the leak from motor rotating shaft
- To reduce the loss of magnetic force inner/outer duct thickness were designed to 3mm/5mm
- Annual inspections of vibration and duct thickness measurement for erosion inspection in every year, bearing grease-up and insulation resistance measurement in every two years

Insulation resistance of pump motor



- Insulation resistance between each phase and earth are measured at the outside of hot-cell
- Results including the effects of motor (class F insulation), connector, rad-hard cables (~40 m)
- Replacement was decided resistance showed near the acceptable value of 1.0 MΩ in 2024

Hot-cell for target maintenance

Hot cell (MLF 1F)

L : 40 m × W : 13 m × H : 12 m

Ventilation

14,500m³/h (2 x volumes/hour)

Separate two area






Mercury area, moderator area

Ceiling hatch : 12×5 (2), 4×4 (1),
2.4×2.4 (5) m





Carry equipments into
hot cell from high-bay

Floor hatch : 2.4×2.4 (3)

Carry used components into
storage room/dry up room



Pump replacement by remote handling





Mercury pump (weight: 3 ton)

- Remote handling test and training were conducted carefully for rubber plug insertion and metal seal replacement using mockup target trolley
- 7 flanges should be opened for pump replacement, and insert rubber plugs to prevent tritium release from opening parts
- Replacement work and leak test were successful but amount of tritium release was slightly larger than expected


Predicted/ Result :141GBq / 160 GBq

Replacement procedure


Loosen bolts for pressure gage




Remove pressure gage
Close opening port





Loosen flange bolts for jumper pipes




Lift jumper pipes
Close opening ports




Close pump flanges





Loosen bolts for pump drain flanges




Lift pump unit and close drain flanges




Replace metal seal of flanges on target trolley





Place mercury pump No.2




Joint inlet jumper pipes





Airtightness test
by vacuum and helium leak



Transport to storage room
after smearing
and dose rate
measurement




Increase of stack radiation monitor during operation




Sniffer helium leak test using manipulator

- Helium leak test was passed but rise of stack monitors counts were detected during beam test before user operation
- Inspection criteria was set to $1\text{E-}6 \text{ Pa}\cdot\text{m}^3/\text{s}$ by focusing on to prevent mercury leakage at that time
- Re-inspection after beam test, tiny gas leak was detected on pump flange $5.8\text{E-}7 \text{ Pa}\cdot\text{m}^3/\text{s}$
- Retightening of flange bolts was not effective to reduce leak, and decided to reduce beam power to 100 kW and to replace flange seal in March


Mockup tests for metal seal replacement



Helium leak detector





150A flange mockup ($\phi 480 \times 40t$)



Target trolley mockup

- To investigate the reason of flange leak and improve the seal replacement procedures by remote handling, mockup tests using flange element and jumper pipe were conducted
- Vacuuming leak test was selected to detect leak in high-precision, although the actual target system is available only sniffer test

Flange structure and cause analysis of flange leak



VALCUA 3645 TRYPACK

Torque and axial force

Metal c-ring with coil spring

Ni-ring, SUS spring

Required line load

490 kN/m for metal seal

$$\pi D = 0.487 \text{ m} \quad F = T / (kd)$$

$$F = 240 \text{ kN} \quad = 200 \text{ Nm} / (0.02 \text{ m} * 0.2)$$

$$= 50 \text{ kN}$$

= 40 kN/bolt Satisfy required force

F: Axial force
D: Seal diameter
6 bolts


T: Tightening torque
k: Torque coefficient (0.1~0.2)
d: bolt diameter

Torque Nm	He leak [Pam ³ /s]	Flange gap at each bolt[mm]				Contact at flange edge				note
		P1	1	2	3	P2	4	5	6	
0		0.6	0.6	0.65	0.65	0.6	0.6	0.6	0.65	Place flange
60		1.45	0.85	0.19	<0.04	0.19	0.75	1.35	1.65	Tighten #3 60 Nm
60		0.6	0.6	0.6	0.65	0.65	0.6	0.6	0.6	Loosen #3 1 rotation
60		0.21	0.75	1.35	1.65	1.45	0.8	0.18	<0.04	Tighten #6 60 Nm
60		0.15	0.08	0.19	0.3	0.55	0.32	<0.04	<0.04	All bolts 60 Nm
120	Vacuum test	0.12	<0.04	<0.04	<0.04	0.17	<0.04	<0.04	<0.04	Turbo pump start
200	5.0E-09	0.07	<0.04	<0.04	<0.04	0.09	<0.04	<0.04	<0.04	


Loose 1 rotation did not
affected for even gap

- Leak was reproduced (5E-8 Pam³/s in vacuum helium leak test) traced scenario at pump replacement bolts tightened 60 Nm (1) → loose 1 rotation → 60 Nm (1,4,6,3,5,2) → 120 Nm(1,4,6,3,5,2) → 200 Nm (1,4,6,3,5,2)
- No leak occurred (<10E-11 Pam³/s) when the bolts were tightened evenly, as an ideal hands tightening procedure


Optimization of procedure for remote handling



Jumper pipe setup by crane and manipulator



Flange gap measurement




Zoom via camera




Decide order of tightening bolt by gap visual inspection

- We learned that the ideal fine-torque management (5–10 Nm steps) is effective for securing leak tightness, but it is not feasible for a power manipulator
- To reproduce the even tightening achieved by manual work using the power manipulator, we conducted 10 flange mock-up tests and 6 jumper-pipe mock-up tests, varying the bolt-tightening procedures to confirm reproducibility
- Based on these results, we decided to focus on achieving even flange gap, rather than managing tightening torque
- The final procedure is: Initial tightening at 20 Nm (sequence: 1, 2, 3, 6, 5, 4), Adjust as needed to achieve an even flange gap at 40–120 Nm, Apply final star-pattern tightening at 160 Nm and 200 Nm


Seal replacement training



Mechanical plug modified for remote handling



Jumper pipe



Flange cleaning by manipulator




Metal seal replacement

Improvements Based on Pump Replacement Experience

- Based on experience during the pump replacement, we changed seal plug for the jumper pipe
- Due to a risk of damaging the sealing surface of flange, we skipped flange cleaning process in pump replacement, but for seal replacement, we decided to add a flange cleaning process for the seal replacement
- We conducted training for the newly added tools and cleaning procedure

Beam operation after seal replacement




Seal plug insertion



Flange cleaning




Seal replacement



- Helium leak test showed below detectable limit for all flanges after seal replacement
- Stuck monitors are recovered usual value in beam operation

Pump power cables replacement



			Total resistance
Jul. 2024	Before pump replacement	Cable+Connector+Pump#1(50 MΩ)	0.8 MΩ
Nov. 2024	After pump replacement	Cable+Connector+Pump#2	3.8 MΩ
Jul. 2025	After 1 year operation	Cable+Connector (0.72 MΩ)+Pump#2 (75 MΩ)	0.27 MΩ
Nov. 2025	After cable replacement	Cable+Connector (7.4 MΩ)+Pump#2 (75 MΩ)	2.7 MΩ


- Rad-hard (5MGy) cable was damaged not only high dose area but also low dose area in 15 years
- Reduction of insulation resistance since cables stored in general area was also damaged

- **Full rad-hard cables and connectors replacement are planned in Oct. 2026**

Summary

- Degradation of insulation resistance for mercury pump was observed after 15 years of operation
- Mercury pump was replaced in Nov. 2024; however, small leak was detected during operation
- To recover from the leak, flange metal seals were replaced using an improved bolt-tightening procedure based on the mock-up tests
- The pump power cables, which had degraded due to radiation and/or aging, were temporarily replaced; installation of radiation-hard cables is planned for Sep. 2026

Working area and environment





- Dose rate map can be measured remotely using crane and ion chamber dosimeter
- Replacement work is performed by full-remote handling, but equipment preparation and cleanup work are done by entering hot-cell with placing additional shielding
- Air contamination is not detected without opening mercury flange
- Tyveck with full-face mask requires for the worker



Remote measurement

Additional shielding

Storage and disposal for used pump issues




Insulation resistance measurement by manipulator


- Opening flanges were closed by blank flange with double seal, and temporarily stored in the storage room
- Using remote measurement tool developed after replacement, we confirmed that the pump has sufficient insulation resistance for use
- Due to the size of hatch to the storage room, pump can not stored in the cask and keep as a spare

Tritium release during replacement

Pump replacement




Seal replacement




	[GBq]	Total	Day1	Day2	Day3
Pump replacement	Ion chamber	268	32	139	97
	Silica gel	160	18	68	74
Seal replacement	Ion chamber	6	6.0	ND	
	Silica gel	7.4	5.2	2.2	

The main reason why the value of the stack ionization box is higher than that of cell silica when replacing the pump is This is because the count of rare gas element nuclei is also evaluated as tritium.


Numerical simulation for metal seal deformation



Pre tension applied to the flange through the bolts





Displacement contour of Z direction



Bolts	Torque		Normalized seal deformation (Value / Max)							
	Nm	P1	1	2	3	P2	4	5	6	
6	200	0.97	0.98	1.00	0.98	0.97	0.98	1.00	0.98	
8	200	1.00	1.00	1.00	1.00	1.00	1.00	0.99	0.99	

- From FEM simulation, current bolt number and layout is enough to deform the metal seal uniformly
- Difference between 6 bolts and 8 bolts are negligible small

Helium leak rate after retightening



Flange cover