



BCM works completed



BCM works to be done + issues

- LEBT ACCT (collimator) to be installed.
- ISRC/LEBT ACCT FE units to be slightly displaced to relieve the pressure on the ACCT cable from the isolation transformer cable trunk.
- uTCA crate in the FEB90 to be replaced.
- BCM test and verification document ESS-0184393 being updated.
- Test and verification (Wetest + manual) under progress.
- **Software:**
 - Lab gateway issue: [INFRA-2922](#)
 - Time axis of the discrete channels on the BCM plots: [ICSHWI-5669](#)

