

BIFROST SAR Documentation Status

05th September 2025

PRESENTED BY: RAVEESH KSHEMA

SAR documentation



Green documents


- Concept of Operations
- Requirements specifications
- P&ID
- System Design Descriptions

Orange documents

- Risk Assessment
- Radiation safety reports
- O&M manuals
- V&V plans

Red documents


- FATs or equivalent
- SATs/Local testing
- Integrated testing reports






Overall documentation Status









Green documentation Status











Orange documentation status











Operation and Maintenance manuals/equivalent





Verification and Validation plans



Red documentation Status








NSS Issue Tracker dashboard



- Project Tool used by NSS to manage, track, and prioritize open issues, critical tasks, related to NSS instrument readiness
- Primary purpose is to log issues, assign responsibilities, set priorities and deadlines and monitor progress on the logged in issues.
- In the context of SAR, all open points related to the Instrument, including open punch list points from various SATs have been logged into this system



Overall Status of unresolved NITs



84





List of NITs to be resolved before TG5/SAR

Open	Done	Bunker	BEER	BIFROST	CSPEC	DREAM	ESTIA	FREIA	HEIMDAL	LOKI	MAGIC	MIRACLES	NMX	ODIN	SKADI	TBL	TREX	VESPA	No Instrument	Inst
ISS Issue 1	Tracker Tickets /	Rich Filter Re	sults																	
Key ‡	Status ‡	Summary \$												Ins	trument ‡	Issu	e source ‡		To be resolved	d before
NIT-310	TO DO	Resize infrastructure support for Bifrost infrastrucutre in the bunker.												BIF	ROST	Inst	allation/SAT	TG5/ SAR		
NIT-306	TO DO	Creation of NICOS warnings for filter vacuum													ROST	Inst	allation/SAT	TG5/ SAR		
NIT-303	TO DO	Enlarge Radius on Beam Stop Borated Aluminium Sheet														Inst	allation/SAT	TG5/ SAR		
NIT-296	IN PROGRESS	BIFROST - Finalize the firmware of the CASCADE monitor													ROST	Cole	d commission	TG5/ SAR		
NIT-295	TO DO	BIFROST - Debug bit/cropping problem in IBM2 DAQ												BIF	ROST	Cole	d commissio	TG5/ SAR		
NIT-294	IN PROGRESS	BIFROST - Release ICD and firmware documentation for the monitor system												BIF	ROST	Inst	allation/SAT		TG5/ SAR	
NIT-293	TO DO	BIFROST - Verify that NICOS can count against fission and CASCADE 14 Hz integrated count numbers												BIF	ROST	Cole	d commission	ning	TG5/ SAR	
NIT-292	TO DO	BIFROST - Test that a 14 Hz integrated count number for fission and CASCADE can be broadcast over Kafka													ROST	Cole	d commissio	ning	TG5/ SAR	
NIT-291	TO DO	BIFROST - Test that aggregated data can be saved in the nexus file													ROST	Cole	d commission	ning	TG5/ SAR	
NIT-290	TO DO	BIFROST -	Verify data	aggregation for	r fission and C	ASCADE monito	rs							BIF	ROST	Cole	d commission	TG5/ SAR		
NIT-289	TO DO	BIFROST -	EFU for Bra	igg peak monito	or									BIF	ROST	Cole	d commissio	TG5/ SAR		
NIT-288	IN PROGRESS	BIFROST -	Verify time	stamping for fis	ssion and CAS	CADE monitors								BIF	ROST	Cole	d commission	TG5/ SAR		
NIT-287	IN PROGRESS	BIFROST -	Confirm da	ita format for fis	sion and CAS	CADE using on s	ite DAQs							BIF	ROST	Cole	d commission	TG5/ SAR		
NIT-286	TO DO	BIFROST -	Test EFU fu	nctionality for fi	ission and CAI	CADE monitors								BIF	ROST	Cole	d commission	ning	TG5/ SAR	
NIT-285	TO DO	BIFROST -	Modify and	d test R5560 firm	nware for Brag	g peak monitor								BIF	ROST	Cole	d commission	TG5/ SAR		
NIT-283	TO DO	BIFROST -	successfully	y deploy and tes	st the slow cor	ntrol of the fission	n monitor							BIF	ROST	Cole	d commission	ning	TG5/ SAR	
NIT-282	TO DO	BIFROST -	successfully	y deploy and tes	st the slow cor	ntrol of CASCAD	E monitor							BIF	ROST	Cole	d commission	ning	TG5/ SAR	
NIT-281	TO DO	BIFROST -	successfully	y deploy all 4 m	onitors on the	same ring								BIF	ROST	Cole	d commission	TG5/ SAR		
NIT-280	TO DO	BIFROST -	Complete r	monitor gas syst	tem									BIF	ROST	Inst	allation/SAT		TG5/ SAR	
NIT-278	TO DO	BIFROST -	resolve 1 O	hm connection	error on bean	n monitors								BIF	ROST	Oth	er		TG5/ SAR	



List of NITs to be resolved before TG5/SAR

Open	Done	Bunker	BEER	BIFROST	CSPEC	DREAM	ESTIA	FREIA	HEIMDAL	LOKI	MAGIC	MIRACLES	NMX	ODIN	SKADI	TBL	TREX	VESPA	No Instrume	
ISS Issue	Tracker Tickets	s / Rich Filter R	esults																	
Кеу ‡	Status ‡	Summary ‡											Instrumen	nt ‡	Issue sour	rce ‡		To be	resolved before \$	
NIT-277	TO DO	BIFROST - m	ark all mon	itor components	with the corre	ect FBS tags							BIFROST		Cold com	missioning		TG5/ S	SAR	
NIT-264	TO DO	Installation o	Installation of borated lining in service feedthroughs												Installatio	n/SAT		TG5/ SAR		
NIT-257	TO DO	BIFROST - Integrate filter vacuum gauge level in NICOS													Cold com	missioning		TG5/ SAR		
NIT-256	TO DO	BIFROST - In	BIFROST - Integrate tank vacuum pressure gauge level in NICOS													missioning		TG5/ SAR		
NIT-255	IN REVIEW	BIFROST - im	nplement N	ICOS warning be	eryllium filter te	emperature							BIFROST		Cold com	missioning		TG5/ S	SAR	
NIT-254	IN REVIEW	BIFROST - im	nplement w	arning in NICOS	for low LN2 le	vel in beryllium	filter						BIFROST		Cold com	missioning		TG5/ S	SAR	
NIT-252	TO DO	Modify hard stop on the Bifrost tank											BIFROST		Installatio	on/SAT		TG5/ S	SAR	
NIT-248	TO DO	Bifrost Cave Hatch Cabinet - Energisation											BIFROST		Installatio	on/SAT		TG5/ S	SAR	
NIT-247	TO DO	ToM is missing some LBS											BIFROST		CDR/TG3	DR/TG3			SAR	
NIT-244	TO DO	Install BIFRO	ST Side Blo	ck in E2									BIFROST		Installatio	on/SAT		TG5/ S	SAR	
NIT-241	TO DO	Grounding o	f Compone	ents in the Bunke	r								BIFROST		Installatio	Installation/SAT			SAR	
NIT-230	TO DO	Bifrost Spect	rometer Po	lyethyelene									BIFROST		Installatio	Installation/SAT			TG5/ SAR	
NIT-228	TO DO	Bifrost Cave	SAT - Lead	Chimneys									BIFROST		Installation/SAT			TG5/ SAR		
NIT-227	TO DO	Bifrost Cave	SAT - Roof	Handrails									BIFROST		Installatio	on/SAT		TG5/ S	SAR	
NIT-155	TO DO	Bifrost shutte	er Absence	of CE-marking o	n equipment o	or an agreed pla	an for CE-mai	king					BIFROST		Q-gate/F	Q-gate/FAT			TG5/ SAR	
NIT-70	TO DO	BIFROST: BM	1 (Cascade)	Pressure									BIFROST		Q-gate/F	AT		Energ	ization	
NIT-46	TO DO	BIFROST: BM	1 (Fission) E	mail Manufacture	er Electrical								BIFROST		Q-gate/F	AT		TG5/ S	SAR	
NIT-45	TO DO	BIFROST: BM	1 (Fission) P	urpose Made Ele	ctrical								BIFROST		Q-gate/F	AT		Energ	ization	
NIT-31	TO DO	BIFROST Inst	rument Ear	thing System									BIFROST		Other			TG5/ 9	SAR	
NIT-6	TO DO	BM gas lines	in bunker										BIFROST					TG5/ 9	SAR	



List of NITs to be resolved before SRR

Open	Done	Bunker	BEER	BIFROST	CSPEC	DREAM	ESTIA	FREIA	HEIMDAL	LOKI	MAGIC	MIRACLES	NMX	ODIN	SKADI	TBL	TREX	VESPA	No Instrument
SS Issue 1	fracker Tick	ets / Rich Filter R	esults																
ζey ≑	Status ‡	Summary ‡												Instrume	nt ‡	Issue sou	urce ‡		To be resolved
NT-297	TO DO	Include Groundii	ng Cable Dis	sconnection in O	&M Manuals									BIFROST	•	Installati	ion/SAT		SRR
NT-279	TO DO	BIFROST - BM1 r	resolve amp	lifier and LV conr	nection issues									BIFROST		Installati	ion/SAT		SRR
NT-276	TO DO	BIFROST - chang	ge LV connec	ctions to BM1 an	d amplifier									BIFROST	•	Other			SRR
NT-274	TO DO	BIFROST - test K	afka streami	ing for all sample	e environment	variables in the	e sample env	ironment tes	t plan					BIFROST	•	Cold cor	mmissioning		SRR
NT-273	TO DO	BIFROST - imple	ment alarm	for cryomagnet	coil temperatu	re being off ta	rget in NICO	5						BIFROST	•	Cold cor	mmissioning		SRR
NT-272	TO DO	BIFROST - Imple	ment an ala	rm for sample er	vironment ter	nperature bein	g off target i	n NICOS						BIFROST	•	Cold cor	mmissioning		SRR
NT-271	TO DO	BIFROST - Imple	ment alarm	for low cryogen	levels on sam	ole environmer	t in NICOS							BIFROST		Cold cor	mmissioning		SRR
IIT-270	TO DO	BIFROST - Imple	ment needle	e valve and cryog	gen display in	NICOS								BIFROST	•	Cold cor	mmissioning		SRR
IIT-269	TO DO	BIFROST - ramp	rate, tempe	rature curve and	setpoint in NI	COS (via Lakes	hore)							BIFROST	•	Cold cor	mmissioning		SRR
NT-268	TO DO	BIFROST - Imple	ment Oxford	d cryomagnet PV	s in NICOS									BIFROST	•	Cold cor	mmissioning		SRR
NT-267	TO DO	BIFROST - Imple	ment all ora	nge cryostat PV'	s in NICOS									BIFROST		Cold cor	mmissioning		SRR
IIT-266	TO DO	Retest of potenti	iometers											BIFROST	•	Cold cor	mmissioning		SRR
NT-265	TO DO	Retesting of Gon	niometers											BIFROST	•	Cold cor	mmissioning		SRR
IIT-263	TO DO	Bifrost False Floo	or North Cor	mpletion										BIFROST		Installati	ion/SAT		SRR
IIT-250	TO DO	Revision of O&N	1 Manual											BIFROST	•	Cold cor	mmissioning		SRR
NT-249	TO DO	Addition and am	endment of	f motion tags in t	the cave									BIFROST		Other			SRR
IIT-245	TO DO	Install BIFROST S	Side Plates											BIFROST	•	Installati	ion/SAT		SRR
IIT-234	TO DO	Bifrost pneumati	ics error han	ndling										BIFROST		Installati	ion/SAT		SRR
NT-232	TO DO	CUP Installation	of IA Manifo	old										BIFROST		Installati	ion/SAT		SRR
IIT-43	TO DO	Bifrost Spectrom	ieter - As Bu	iilt										BIFROST		Installati	ion/SAT		SRR
IIT-42	TO DO	As Built - Guide a	and Frame i	n Cave										BIFROST		Installati	ion/SAT		SRR
IIT-30	TO DO	Goniometers C.C	D.G problem	ı fix										BIFROST		Installati	ion/SAT		SRR
IIT-18	TO DO	Update O&M ma	anual Bifros	t Beryllium filter										BIFROST		Q-gate/	FAT		SRR



List of NITs to be resolved before ORR

Open	Done	Bunker	BEER	BIFROST	CSPEC	DREAM	ESTIA	FREIA	HEIMDAL	LOKI	MAGIC	MIRACLES	NMX	ODIN	SKADI	TBL	TREX	VESPA	No Instrument
ISS Issue T	racker Tickets	/ Rich Filter R	lesults																
Key ≑	Status ‡	Summary ‡												Instrument ‡		Issue source	<u>.</u> 7		To be resolved before
VIT-284	TO DO	BIFROST - d	eploy and te	est backend rack	PDU control f	or RMM power	cycling							BIFROST		Cold commis	sioning		TG6/ ORR
NIT-275	TO DO	BIFROST - in	nplement sa	ample environme	ent and sensor	IDs to be writt	en in the nex	us file						BIFROST	(Other			TG6/ ORR
VIT-262	TO DO	BIFROST - D	etector: Fine	etune firmware r	egistries to ma	iximize gamma	suppression	and efficienc	y					BIFROST	(Cold commis	sioning		TG6/ ORR
NIT-261	IN REVIEW	BIFROST - D	etector gro	up to document	He-3 PSD tub	e firmware								BIFROST	(Cold commis	sioning		TG6/ ORR
NIT-260	TO DO	BIFROST - Te	est RMM tin	ning using gener	al NSS metho	d								BIFROST	(Cold commis	sioning		TG6/ ORR
NIT-259	TO DO	BIFROST - In	nplement se	etting firmware n	egistries on in	dividual DAQs								BIFROST	(Cold commis	sioning		TG6/ ORR
NIT-258	TO DO	BIFROST - re	eplace bad r	esistor on 2.7 me	eV, 2, detector	module								BIFROST	(Cold commis	sioning		TG6/ ORR
NIT-251	TO DO	Installation of	of Borated P	oly Plug in Cave	Wall									BIFROST	(Cold commis	sioning		TG6/ ORR
NIT-246	TO DO	Precision tin	ne stamping	for motor posit	ions									BIFROST	(Cold commis	sioning		TG6/ ORR
NIT-243	TO DO	BIFROST Bui	nker choppe	er system Isolatio	n not done									BIFROST	(Other			TG6/ ORR
NIT-242	TO DO	BIFROST Co	oling SAT do	ocument missing										BIFROST	(Other			TG6/ ORR
NIT-231	TO DO	Bifrost - Ben	yllium Filter	Adjustment Syst	em Amendme	nts								BIFROST	1	Installation/S	AT		TG6/ ORR
NIT-226	TO DO	Bifrost Cave	SAT - Roof	Beam Gaps										BIFROST	I	Installation/S	AT		TG6/ ORR
NIT-224	TO DO	Bifrost Analy	yser - Perfor	mance Check										BIFROST	I	Installation/S	AT		TG6/ ORR
NIT-144	TO DO	As-Built Dra	wings for M	CAG Scope										BIFROST	(Cold commis	sioning		TG6/ ORR
NIT-143	TO DO	Shutter Swit	ch Junction	Box										BIFROST	(Cold commis	sioning		TG6/ ORR
NIT-142	TO DO	Amendment	t of Attenua	tor 1 Valve and A	Attenuator Tag	S								BIFROST	(Cold commis	sioning		TG6/ ORR
NIT-82	TO DO	Bifrost BM4	- Magnetisr	n										BIFROST	1	Installation/S	AT		TG6/ ORR
NIT-35	TO DO	Change BIFF	ROST BBGO	A drawing title										BIFROST	(Other			TG6/ ORR
NIT-29	TO DO	Stainless ste	el parts on I	BE filter										BIFROST	1	Installation/S	AT		TG6/ ORR
NIT-21	TO DO	Change thru	ist screw to	non-magnetic -	Bifrost									BIFROST		Installation/S	AT		TG6/ ORR



Questions?