

## **BIFROST SAR Documentation Status**

05<sup>th</sup> September 2025

**PRESENTED BY: RAVEESH KSHEMA** 

#### SAR documentation



#### Green documents


- Concept of Operations
- Requirements specifications
- P&ID
- System Design Descriptions


#### Orange documents

- Risk Assessment
- Radiation safety reports
- O&M manuals
- V&V plans

#### Red documents


- FATs or equivalent
- SATs/Local testing
- Integrated testing reports






#### Overall documentation Status









#### Green documentation Status









### Orange documentation status













#### Red documentation Status








#### NSS Issue Tracker dashboard



- Project Tool used by NSS to manage, track, and prioritize open issues, critical tasks, related to NSS instrument readiness
- Primary purpose is to log issues, assign responsibilities, set priorities and deadlines and monitor progress on the logged in issues.
- In the context of SAR, all open points related to the Instrument, including open punch list points from various SATs have been logged into this system



#### Overall Status of unresolved NITs



82





## List of NITs to be resolved before TG5/SAR

Open	Done	Bunker	BEER	BIFROST	CSPEC	DREAM	ESTIA	FREIA	HEIMDAL	LOKI	MAGIC	MIRACLES	NMX	ODIN	SKADI	TBL	TREX	VESPA	No Instrument		
NSS Issue T	Fracker Tickets	: / Rich Filter R	esults																		
Key <b>‡</b>	Status ‡	Summary ‡											Instrumen	it ‡	Issue sou	rce ‡		To be	resolved before \$		
NIT-30	TO DO	Goniometers	C.O.G prob	olem fix									BIFROST		Installatio	on/SAT		TG5/	SAR		
NIT-31	TO DO	BIFROST Inst	rument Earl	thing System									BIFROST		Other	er TG5/ SAR					
NIT-42	TO DO	As Built - Guide and Frame in Cave													Installatio	on/SAT		TG5/ SAR			
NIT-43	TO DO	Bifrost Spectrometer - As Built													Installatio	on/SAT		TG5/ SAR			
NIT-46	TO DO	BIFROST: BM	l (Fission) Er	mail Manufacture	er Electrical								BIFROST		Q-gate/F	AT	TG5/ SAR				
NIT-155	TO DO	Bifrost shutte	er Absence	of CE-marking o	n equipment o	r an agreed pla	n for CE-mar	king					BIFROST		Q-gate/F	AT		TG5/	SAR		
NIT-227	TO DO	Bifrost Cave SAT - Roof Handrails										BIFROST		Installatio	on/SAT		TG5/	SAR			
NIT-228	TO DO	Bifrost Cave SAT - Lead Chimneys										BIFROST		Installatio	on/SAT		TG5/	SAR			
NIT-230	TO DO	Bifrost Spectrometer Polyethyelene										BIFROST		Installatio	on/SAT		TG5/	SAR			
NIT-232	TO DO	CUP Installat	ion of IA M	anifold									BIFROST		Installatio	on/SAT		TG5/	SAR		
NIT-241	TO DO	Grounding o	f Compone	nts in the Bunke	r								BIFROST		Installatio	on/SAT		TG5/ SAR			
NIT-244	TO DO	Install BIFRO	ST Side Blo	ck in E2									BIFROST	BIFROST Installation/SA				SAT TG5/ SAR			
NIT-252	TO DO	Modify hard	stop on the	Bifrost tank									BIFROST	Installatio	Installation/SAT			TG5/ SAR			
NIT-254	IN REVIEW	BIFROST - im	plement wa	arning in NICOS	for low LN2 le	vel in beryllium	filter						BIFROST		Cold con	nmissioning		TG5/ SAR			
NIT-255	IN REVIEW	BIFROST - im	plement N	ICOS warning be	ryllium filter te	emperature							BIFROST		Cold con	nmissioning		TG5/	SAR		
NIT-256	TO DO	BIFROST - In	tegrate tanl	k vacuum pressu	re gauge level	in NICOS							BIFROST		Cold con	nmissioning		TG5/	SAR		
NIT-257	TO DO	BIFROST - In	tegrate filte	r vacuum gauge	level in NICO	5							BIFROST		Cold con	nmissioning		TG5/	SAR		
NIT-264	TO DO	Installation o	of borated li	ning in service fe	edthroughs								BIFROST Installation/SAT					TG5/ SAR			
NIT-277	TO DO	BIFROST - ma	ark all moni	itor components	with the corre	ect FBS tags							BIFROST Cold commissioning					TG5/ SAR			
NIT-278	TO DO	BIFROST - re	solve 1 Ohr	n connection err	or on beam m	onitors							BIFROST		Other			TG5/	SAR		



## List of NITs to be resolved before TG5/SAR

Open	Done	Bunker	BEER	BIFROST	CSPEC	DREAM	ESTIA	FREIA	HEIMDAL	LOKI	MAGIC	MIRACLES	NMX	ODIN	SKADI	TBL	TREX	VESPA	No Instrument	TG5,
ISS Issue 1	Fracker Tickets /	Rich Filter Re	sults																	
<ey td="" ‡<=""><td>Status ‡</td><td>Summary ‡</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>Ins</td><td>strument ‡</td><td>Issu</td><td>ue source ‡</td><td></td><td>To be resolve</td><td>before</td></ey>	Status ‡	Summary ‡												Ins	strument ‡	Issu	ue source ‡		To be resolve	before
VIT-280	TO DO	BIFROST -	Complete m	nonitor gas syste	em									BII	FROST	Inst	tallation/SAT		TG5/ SAR	
VIT-281	TO DO	BIFROST -	successfully	deploy all 4 mo	nitors on the	same ring								BII	FROST	Col	ld commissio	ning	TG5/ SAR	
VIT-282	TO DO	BIFROST -	successfully	deploy and test	t the slow con	trol of CASCAD	E monitor							BII	FROST	Col	ld commission	oning	TG5/ SAR	
VIT-283	TO DO	BIFROST -	successfully	deploy and test	t the slow con	trol of the fission	n monitor							BII	FROST	Col	ld commissio	oning	TG5/ SAR	
VIT-285	TO DO	BIFROST -	Modify and	test R5560 firm	ware for Brag	g peak monitor								BII	FROST	Col	ld commissio	oning	TG5/ SAR	
VIT-286	TO DO	BIFROST -	Test EFU fun	nctionality for fis	sion and CAD	CADE monitors								BII	FROST	Col	ld commissio	oning	TG5/ SAR	
VIT-287	IN PROGRESS	BIFROST -	Confirm dat	ta format for fiss	sion and CASC	ADE using on s	ite DAQs							BII	FROST	Col	ld commissio	oning	TG5/ SAR	
VIT-288	IN PROGRESS	BIFROST -	Verify time s	stamping for fiss	sion and CASC	ADE monitors								BII	FROST	Col	ld commissio	oning	TG5/ SAR	
VIT-289	TO DO	BIFROST -	EFU for Brag	gg peak monito	r									BII	FROST	Col	ld commissio	oning	TG5/ SAR	
VIT-290	TO DO	BIFROST -	Verify data a	aggregation for	fission and CA	SCADE monito	rs							BII	FROST	Col	ld commissio	oning	TG5/ SAR	
VIT-291	TO DO	BIFROST -	Test that ag	gregated data c	an be saved ir	the nexus file								BII	FROST	Col	ld commissio	oning	TG5/ SAR	
VIT-292	TO DO	BIFROST -	Test that a 1	14 Hz integrated	count number	r for fission an	d CASCADE o	an be broad	cast over Kafka					BII	FROST	Col	ld commissio	oning	TG5/ SAR	
VIT-293	TO DO	BIFROST -	Verify that N	NICOS can count	t against fissio	n and CASCAD	E 14 Hz integ	rated count	numbers					BII	FROST	Col	ld commissio	oning	TG5/ SAR	
VIT-294	IN PROGRESS	BIFROST -	Release ICD	and firmware d	ocumentation	for the monito	r system							BII	FROST	Inst	tallation/SAT		TG5/ SAR	
VIT-295	TO DO	BIFROST -	Debug bit/c	ropping proble	m in IBM2 DA	Q								BII	FROST	Col	ld commissio	oning	TG5/ SAR	
VIT-296	IN PROGRESS	BIFROST -	Finalize the	firmware of the	CASCADE mo	nitor								BII	FROST	Col	ld commissio	oning	TG5/ SAR	
VIT-303	TO DO	Enlarge Ra	dius on Bear	m Stop Borated	Aluminium Sh	neet								BII	FROST	Inst	tallation/SAT		TG5/ SAR	
VIT-306	TO DO	Creation of	f NICOS war	rnings for filter v	acuum/									BII	FROST	Inst	tallation/SAT		TG5/ SAR	
VIT-320	TO DO	BM1 Patch	Panel and F	RH										BII	FROST	Oth	her		TG5/ SAR	
VIT-328	TO DO	Pipework o	ver Bifrost F	FOC1										BII	FROST	Inst	tallation/SAT		TG5/ SAR	



#### List of NITs to be resolved before SRR

Open	Done	Bunker	BEER	BIFROST	CSPEC	DREAM	ESTIA	FREIA	HEIMDAL	LOKI	MAGIC	MIRACLES	NMX	ODIN	SKADI	TBL	TREX	VESPA	No Instrument
		cets / Rich Filter I	Results											Instrume		Issue soi			To be resolved be
Key ‡ NIT-297	TO DO	Summary \$	ina Cabla Di	sconnection in C	NO. M. Manuale									BIFROST		Installat			SRR
NIT-297 NIT-279	TO DO		_	olifier and LV con										BIFROST		Installat			SRR
NIT-279 NIT-276	TO DO			ctions to BM1 ar										BIFROST		Other	ION/SAI		SRR
NIT-276	TO DO		-	ing for all sampl		variables in th	o cample on	ironmont too	t plan					BIFROST			mmissioning		SRR
NIT-274	TO DO			for cryomagnet					t pian					BIFROST			mmissioning		SRR
NIT-273	TO DO			arm for sample e			-							BIFROST			mmissioning		SRR
NIT-272	TO DO			for low cryogen		•		II NICO3						BIFROST			mmissioning		SRR
NIT-271	TO DO			e valve and cryo			IL III INICOS							BIFROST			mmissioning		SRR
NIT-269	TO DO			erature curve and			hore)							BIFROST			mmissioning		SRR
NIT-268	TO DO			d cryomagnet P\		CO3 (VIa Lakes	nore)							BIFROST			mmissioning		SRR
NIT-267	TO DO			ange cryostat PV										BIFROST			mmissioning		SRR
NIT-266	TO DO	Retest of poten		ange cryostaer v	3111111000									BIFROST			mmissioning		SRR
NIT-265	TO DO	Retesting of Go												BIFROST			mmissioning		SRR
NIT-263	TO DO	Bifrost False Flo		mpletion										BIFROST		Installat			SRR
NIT-250	TO DO	Revision of O&I												BIFROST			mmissioning		SRR
NIT-249	TO DO			f motion tags in	the cave									BIFROST		Other	9		SRR
NIT-245	TO DO	Install BIFROST												BIFROST		Installat	ion/SAT		SRR
NIT-234	TO DO	Bifrost pneuma		ndlina										BIFROST		Installat			SRR
NIT-18				t Beryllium filter										BIFROST		Q-gate/			SRR



#### List of NITs to be resolved before ORR

Open	Done	Bunker	BEER	BIFROST	CSPEC	DREAM	ESTIA	FREIA	HEIMDAL	LOKI	MAGIC	MIRACLES	NMX	ODIN	SKADI	TBL	TREX	VESPA	No Instrument
ISS Issue T	racker Tickets	/ Rich Filter R	lesults																
Key ≑	Status ‡	Summary ‡												Instrument ‡		Issue source	<u>.</u> 7		To be resolved before
VIT-284	TO DO	BIFROST - d	eploy and te	est backend rack	PDU control f	or RMM power	cycling							BIFROST		Cold commis	sioning		TG6/ ORR
NIT-275	TO DO	BIFROST - in	nplement sa	ample environme	ent and sensor	IDs to be writt	en in the nex	us file						BIFROST	(	Other			TG6/ ORR
VIT-262	TO DO	BIFROST - D	etector: Fine	etune firmware r	egistries to ma	iximize gamma	suppression	and efficienc	y					BIFROST	(	Cold commis	sioning		TG6/ ORR
NIT-261	IN REVIEW	BIFROST - D	etector gro	up to document	He-3 PSD tub	e firmware								BIFROST	(	Cold commis	sioning		TG6/ ORR
NIT-260	TO DO	BIFROST - Te	est RMM tin	ning using gener	al NSS metho	d								BIFROST	(	Cold commis	sioning		TG6/ ORR
NIT-259	TO DO	BIFROST - In	nplement se	etting firmware n	egistries on in	dividual DAQs								BIFROST	(	Cold commis	sioning		TG6/ ORR
NIT-258	TO DO	BIFROST - re	eplace bad r	esistor on 2.7 me	eV, 2, detector	module								BIFROST	(	Cold commis	sioning		TG6/ ORR
NIT-251	TO DO	Installation of	of Borated P	oly Plug in Cave	Wall									BIFROST	(	Cold commis	sioning		TG6/ ORR
NIT-246	TO DO	Precision tin	ne stamping	for motor posit	ions									BIFROST	(	Cold commis	sioning		TG6/ ORR
NIT-243	TO DO	BIFROST Bui	nker choppe	er system Isolatio	n not done									BIFROST	(	Other			TG6/ ORR
NIT-242	TO DO	BIFROST Co	oling SAT do	ocument missing										BIFROST	(	Other			TG6/ ORR
NIT-231	TO DO	Bifrost - Ben	yllium Filter	Adjustment Syst	em Amendme	nts								BIFROST	1	Installation/S	AT		TG6/ ORR
NIT-226	TO DO	Bifrost Cave	SAT - Roof	Beam Gaps										BIFROST	I	Installation/S	AT		TG6/ ORR
NIT-224	TO DO	Bifrost Analy	yser - Perfor	mance Check										BIFROST	I	Installation/S	AT		TG6/ ORR
NIT-144	TO DO	As-Built Dra	wings for M	CAG Scope										BIFROST	(	Cold commis	sioning		TG6/ ORR
NIT-143	TO DO	Shutter Swit	ch Junction	Box										BIFROST	(	Cold commis	sioning		TG6/ ORR
NIT-142	TO DO	Amendment	t of Attenua	tor 1 Valve and A	Attenuator Tag	S								BIFROST	(	Cold commis	sioning		TG6/ ORR
NIT-82	TO DO	Bifrost BM4	- Magnetisr	n										BIFROST	1	Installation/S	AT		TG6/ ORR
NIT-35	TO DO	Change BIFF	ROST BBGO	A drawing title										BIFROST	(	Other			TG6/ ORR
NIT-29	TO DO	Stainless ste	el parts on I	BE filter										BIFROST	1	Installation/S	AT		TG6/ ORR
NIT-21	TO DO	Change thru	ist screw to	non-magnetic -	Bifrost									BIFROST		Installation/S	AT		TG6/ ORR



# Questions?